



AP Display Panels for Metallic Rods

AP 5-14 AP 7-14 AP 9-14 AP 11-14
 AP 5-20 AP 7-20 AP 9-20 AP 11-20




	I	J	K	L
AP 5-14	2 x 12H/18	4 x	4 x	8 x
AP 7-14	3 x 12H/18	6 x	6 x	12 x
AP 9-14	4 x 12H/18	8 x	8 x	16 x
AP 11-14	5 x 12H/18	10 x	10 x	20 x
AP 5-20	2 x 18H/24	4 x	4 x	8 x
AP 7-20	3 x 18H/24	6 x	6 x	12 x
AP 9-20	4 x 18H/24	8 x	8 x	16 x
AP 11-20	5 x 18H/24	10 x	10 x	20 x




B	C	D	E	F	G	H
4x	4x	4x	4x	4x	4x	1x
*6x	*6x	*6x	6x	6x	6x	1x




Wall mounting



Step 1



Step 2



Step 4